



XIRIUM PRO

XIRIUM PRO App & Firmware

Version history - Issues & solutions





Firmware on XIRIUM PRO device		App
App Control Firmware	XIRIUM PRO Firmware	
App Control firmware NACF-Dec052014 <i>released in December, 2015</i> - Initial release	XIRIUM PRO firmware 1.0 <i>released in December, 2015</i> - Initial release	XIRIUM PRO app 1.0 <i>released in December, 2015</i> - Initial release
	XIRIUM PRO firmware 1.1 <i>released in February, 2016</i> - Packet-loss indication - Unlink support XIRIUM PRO firmware 1.2 <i>released in February, 2016</i> - Bug fix	XIRIUM PRO app 1.1 <i>released in February, 2016</i> - Monitoring signal strength and packet-loss - Unlink RX from TX; dragging to “available devices”
App Control firmware NACF-Oct222015 <i>released in April, 2016</i> - Bug Fix	XIRIUM PRO firmware 2.0 <i>released in April, 2016</i> - Mute on RX - Country specific settings - Optimized battery algorithm and display - Optimized RSSI display	XIRIUM PRO app 2.0 <i>released in April, 2016</i> - Mute switch in RX EDIT mode - Country specific settings / Touring-option - Optimized battery algorithm and display - Optimized RSSI display
	XIRIUM PRO firmware 2.1 <i>released in August, 2016</i> - Bug fix	XIRIUM PRO app 2.1 <i>released in August 2016</i> - Bug fix - UAE included in zone 3
		XIRIUM PRO app 2.1.1 <i>released in September, 2016</i> only an iOS release! - iOS 10 compatible
App Control firmware NACF-Aug122016 <i>released in February, 2017</i> - Bug Fix <div style="background-color: yellow; padding: 2px; display: inline-block;">Latest version!</div>	XIRIUM PRO firmware 3.0 <i>released in February, 2017</i> - Advanced Mode - Device Temperature Indication	XIRIUM PRO app 3.0 <i>released in February, 2017</i> - RF Attenuator - Hide SSID option - Device Temperature Indication - Bug fixes - Australia, New Zealand, Hong Kong included in zone 2



Firmware on XIRIUM PRO device		App
App Control Firmware	XIRIUM PRO Firmware	
	<p>XIRIUM PRO firmware 3.1 <i>released in June, 2017</i></p> <ul style="list-style-type: none"> - Bug fixes - Optimizations - Adjusted Hardware Reset (sets attenuator to off) 	<p>XIRIUM PRO app 3.1 <i>released in June, 2017</i></p> <ul style="list-style-type: none"> - support for FW 3.1
	<p>XIRIUM PRO firmware 3.2 <i>released in October, 2017</i></p> <ul style="list-style-type: none"> - Major Bug fixes - Optimizations 	<p>XIRIUM PRO app 3.2 <i>released in October, 2017</i></p> <ul style="list-style-type: none"> - support for FW 3.2 - iOS 11 compatible - Mounting Guide update
	<p>XIRIUM PRO firmware 4.0 <i>released in July, 2018</i></p> <ul style="list-style-type: none"> - Auto reboot function - Manual restart function - No RX attenuator toggling during scan - RX Dante Link problem fixed - Smaller Bug fixes <p style="text-align: right;">Latest version!</p>	<p>XIRIUM PRO app 4.0 <i>released in July, 2018</i></p> <ul style="list-style-type: none"> - support for FW 4.0 - Mounting Guide update - Integrated DEMO app in Help section - Sweet Spot bracket within signal quality bar - Small changes in Transmission Power window <p style="text-align: right;">Latest version!</p>

Neutrik strongly recommends to keep the devices and the app up-to-date!

Since App version 2.0 and FW version 2.0 every FW update will be communicated to users via the app. The user will be informed by the app store / play store if there is a new app version available. If the user downloads the latest app but uses an old firmware on the device there will be a message in the app with a recommendation to update the devices to make use of all the new features in the app.